

Hardness Value						
Durometer Type	A	B	C	D	O	OO
100	85	77	58			
95	81	70	46			
90	76	59	39			
85	71	52	33			
80	66	47	29	84	98	
75	62	42	25	79	97	
70	56	37	22	75	95	
65	51	32	19	72	94	
60	47	28	16	69	93	
55	42	24	14	65	91	
50	37	20	12	61	90	
45	32	17	10	57	88	
40	27	14	8	53	86	
35	22	12	7	48	83	
30	17	9	6	42	80	
25	12			35	76	
20	6			28	70	
15				21	62	
10				14	55	
5				8	45	

The hardness values listed above are approximate and should only be used as a durometer selection guide.